News January 2025





Shock absorber

HITACHI No. 2017210 / TOKICO No. B2254		HITACHI No. 2017871 / TOKICO No. B2263			
	ΤΟΥΟΤΑ	4851052610		NISSAN	543021A20A
	ΤΟΥΟΤΑ	4851059555		NISSAN	543021A20C
	ΤΟΥΟΤΑ	4851059765		NISSAN	54302CY00B
	ΤΟΥΟΤΑ	4851052490	A BOARD	NISSAN	E43021A20A
	ΤΟΥΟΤΑ	4851059565	0	NISSAN	E4302CY00B

HITACHI No. 2017872 / TOKICO No. B2264		HITACHI No. 2016738 / TOKICO No. B2368			
	NISSAN	543031A20A		MAZDA	DA6A34700A
	NISSAN	543031A20C		MAZDA	DB5P34700A
The second	NISSAN	54303CY00B			
	NISSAN	E43031A20A			
e	NISSAN	E4303CY00B			

HITACHI No. 2016739 / TOKICO No. B2369		HITACHI No. 2016752 / TOKICO No. B3226			
	MAZDA	DA6A34900A		ΤΟΥΟΤΑ	4851029745
	MAZDA	DB5P34900A		ΤΟΥΟΤΑ	4851029755
1 des			The	ΤΟΥΟΤΑ	4851029756
				ΤΟΥΟΤΑ	485102B210
			ø	ΤΟΥΟΤΑ	4851080198

HITACHI No. 2016753 / TOKICO No. B3227		HITACHI No. 2017971 / TOKICO No. U2971			
	ΤΟΥΟΤΑ	4852029455		NISSAN	562104M425
The second secon	ΤΟΥΟΤΑ	4852029465	-	NISSAN	562104M426
	ΤΟΥΟΤΑ	4852029466		NISSAN	562104Z625
	ΤΟΥΟΤΑ	485202B210		NISSAN	562108M400
	ΤΟΥΟΤΑ	4852080033		NISSAN	E62105M425



OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.