




<https://aftermarket.hitachiastemo.com/emea>


Sensor, exhaust gas temperature


HÜCO No. 135574 / HITACHI No. 2505574		
	VW	03L906088DN


HÜCO No. 135575 / HITACHI No. 2505575		
	CHEVROLET	25183660
	CHEVROLET	96994636
	OPEL	25183660
	OPEL	4817518
	OPEL	4818657


HÜCO No. 135576 / HITACHI No. 2505576		
	CHEVROLET	96994638
	CHEVROLET	25183664
	OPEL	4817520
	OPEL	4818660


HÜCO No. 135577 / HITACHI No. 2505577		
	CHEVROLET	96436269
	OPEL	25183665
	OPEL	4803539
	OPEL	4818661


HÜCO No. 135578 / HITACHI No. 2505578		
	AUDI	8K0906088C

HÜCO No. 135579 / HITACHI No. 2505579		
	CHEVROLET	96868940
	OPEL	4818225

HÜCO No. 135580 / HITACHI No. 2505580		
	AUDI	03G906088AA
	AUDI	4F0906088

HÜCO No. 135582 / HITACHI No. 2505582		
	PORSCHE	95860628820
	VW	059906088BP

HÜCO No. 135583 / HITACHI No. 2505583		
	VW	076906088E

HÜCO No. 135584 / HITACHI No. 2505584		
	VW	076906088A
	VW	076906088F


OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.


You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.


Astemo


<https://aftermarket.hitachiastemo.com/emea>


Sensor, exhaust gas temperature


HÜCO No. 135585 / HITACHI No. 2505585		
	VW	03L906088AN
	VW	03L906088DJ


HÜCO No. 135586 / HITACHI No. 2505586		
	MERCEDES-BENZ	A0009050632


HÜCO No. 135587 / HITACHI No. 2505587		
	LANCIA	51795801
	LANCIA	55209555


HÜCO No. 135588 / HITACHI No. 2505588		
	PORSCHE	95860628801
	VW	059906088BL
	VW	059906088BN

HÜCO No. 135589 / HITACHI No. 2505589		
	CHEVROLET	25183656
	CHEVROLET	25205267
	CHEVROLET	96832667
	OPEL	25183656
	OPEL	25205267

HÜCO No. 135590 / HITACHI No. 2505590		
	VW GROUP	04L906088DH

HÜCO No. 135591 / HITACHI No. 2505591		
	VW	059906088BM
	VW	059906088CD

HÜCO No. 135592 / HITACHI No. 2505592		
	VW	03L906088BP
	VW	03L906088HJ

HÜCO No. 135593 / HITACHI No. 2505593		
	AUDI	4H0906088F

HÜCO No. 135594 / HITACHI No. 2505594		
	OPEL	55565652
	OPEL	855255

<https://aftermarket.hitachiastemo.com/emea>

Ignition Coil

HÜCO No. 133980 / HITACHI No. 2503980	
	HYUNDAI / KIA 273103L000

HÜCO No. 133981 / HITACHI No. 2503981	
	HYUNDAI / KIA 273103L030


HÜCO No. 133982 / HITACHI No. 2503982	
	VOLVO 31437796 VOLVO 31492125

HÜCO No. 133983 / HITACHI No. 2503983	
	HONDA 3052059B003 HONDA 3052059B013

HÜCO No. 133984 / HITACHI No. 2503984	
	HYUNDAI / KIA 273012B120

HÜCO No. 133985 / HITACHI No. 2503985	
	VOLVO 31312514

Starter

HITACHI No. 2506963	
on request	HITACHI S25164A UD TRUCKS 23300Z5515
	



Check our YouTube Channel for new videos.

Visit us on  YouTube

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

Astemo