






Visit our website

Shock Absorber

HITACHI No. 2016711 / TOKICO No. B3311		
	mitsubishi	MR319792
	mitsubishi	MR353742
	mitsubishi	MR455401
	mitsubishi	MR554800

HITACHI No. 2016712 / TOKICO No. G35084		
	MAZDA	N12128700

HITACHI No. 2016713 / TOKICO No. B3478		
	SUBARU	20360FC100
	SUBARU	20360FC101
	SUBARU	20360FC120
	SUBARU	20360FC140

HITACHI No. 2016714 / TOKICO No. B3479		
	SUBARU	20360FC110
	SUBARU	20360FC111
	SUBARU	20360FC130
	SUBARU	20360FC150

HITACHI No. 2017290 / TOKICO No. B2227		
	mitsubishi	MR316070
	mitsubishi	SW604063
	mitsubishi	SW604189

HITACHI No. 2017291 / TOKICO No. B2228		
	mitsubishi	MR316069
	mitsubishi	SW604062
	mitsubishi	SW604188

HITACHI No. 2017503 / TOKICO No. A1066		
	NISSAN	5530251Y00
	NISSAN	5530254Y25
	NISSAN	5530258Y25
	NISSAN	5530269Y00
	NISSAN	5530272Y25

HITACHI No. 2017504 / TOKICO No. A1067		
	NISSAN	5530351Y00
	NISSAN	5530354Y25
	NISSAN	5530358Y25
	NISSAN	5530369Y00
	NISSAN	5530372Y25

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

Astemo



Visit our website

Shock Absorber

HITACHI No. 2017509 / TOKICO No. A2218



<p> MITSUBISHI MB891694 MITSUBISHI MB891700 MITSUBISHI MB914964 MITSUBISHI MR197214 MITSUBISHI MR197226 </p>

HITACHI No. 2017510 / TOKICO No. A2219



<p> MITSUBISHI MB891693 MITSUBISHI MB891697 MITSUBISHI MB914963 MITSUBISHI MB914965 MITSUBISHI MR197225 </p>

HITACHI No. 2017514 / TOKICO No. A3064



<p> NISSAN 5530258C25 NISSAN 5530260C20 NISSAN 5530260C28 NISSAN 5530262Y00 NISSAN 5530262Y26 </p>

HITACHI No. 2017515 / TOKICO No. A3065



<p> NISSAN 5530358C25 NISSAN 5530360C20 NISSAN 5530360C28 NISSAN 5530360Y00 NISSAN 5530362Y26 </p>

HITACHI No. 2017520 / TOKICO No. A3090



<p> TOYOTA 4851009400 TOYOTA 4851019435 TOYOTA 485101A130 TOYOTA 4851080008 TOYOTA 4851087700 </p>

HITACHI No. 2017522 / TOKICO No. A3091



<p> TOYOTA 4852009340 TOYOTA 4852012860 TOYOTA 4852019395 TOYOTA 4852019425 TOYOTA 4852019595 </p>

HITACHI No. 2017542 / TOKICO No. B2192



<p> MAZDA B2HK28700 MAZDA BC1E28700A MAZDA BC1E28700D MAZDA BC1H28700B </p>

HITACHI No. 2017543 / TOKICO No. B2193



<p> MAZDA B2HK28900 MAZDA BC1E28900A MAZDA BC1E28900D MAZDA BC1H28900B </p>



Visit our website

Shock Absorber

HITACHI No. 2017555 / TOKICO No. B2212



NISSAN	543020M214
NISSAN	543020M664
NISSAN	543020M964
NISSAN	543020N601
NISSAN	543020N629

HITACHI No. 2017556 / TOKICO No. B2213



NISSAN	543030M214
NISSAN	543030M626
NISSAN	543030M726
NISSAN	543030M925
NISSAN	543030N629

HITACHI No. 2017570 / TOKICO No. B2288



HONDA	51601SAAE02
HONDA	51601SAAG02
HONDA	51601SAAJ15
HONDA	51605SAA033
HONDA	51605SADP02

HITACHI No. 2017571 / TOKICO No. B2289



HONDA	51602SAAE02
HONDA	51602SAAG02
HONDA	51602SAAJ15
HONDA	51606SAA033
HONDA	51606SADP02

automechanika
DUBAI

2 – 4 October 2023
Dubai World Trade Centre

HITACHI
Inspire the Next
Hall 2 Stand D42

EQUIP AUTO 2023
REINVENTING SERVICES FOR MOBILITY

LYON | FROM 28 TO 30
SEPTEMBER 2023
EUREXPO LYON

We'll be there!
WILL YOU?

HITACHI
Inspire the Next

OUR STAND ▶ **6 H 138**



Check our YouTube Channel for new videos.

Visit us on **YouTube**

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

Astemo