

¿ Cansado de reuniones virtuales ?  
**¡ Venga a vernos a Frankfurt  
 en Automechanika 2022 !**

**Pabellón 3.0  
 Stand E60**


**AUTOMECHANIKA 2022**

**Del 13 al 17 de Septiembre  
 Frankfurt, Alemania**

## Sensor temperatura de gas de escape


HÜCO No. 135553 / HITACHI No. 2505553		
	GM	55574938
	OPEL	855286

HÜCO No. 135555 / HITACHI No. 2505555		
	GM	55591174
	GM	55596171
	OPEL	1247640
	OPEL	1247888


HÜCO No. 135556 / HITACHI No. 2505556		
	GENERAL MOTORS	55486951
	GENERAL MOTORS	55495556
	OPEL	1247905
	OPEL	1249065
	OPEL	6237314


HÜCO No. 135557 / HITACHI No. 2505557		
	VW GROUP	04L919529D


## Sensor temperatura de gas de escape


HÜCO No. 135558 / HITACHI No. 2505558		
	VW GROUP	04L919529E

HÜCO No. 135559 / HITACHI No. 2505559		
	VW GROUP	4G0906088B
	VW GROUP	4G0906088G
	VW GROUP	8K0906088A
	VW GROUP	8K0906088D


HÜCO No. 135560 / HITACHI No. 2505560		
	GENERAL MOTORS	55570089
	OPEL	1247511

HÜCO No. 135561 / HITACHI No. 2505561		
	GENERAL MOTORS	55592366
	OPEL	1247806


HÜCO No. 135562 / HITACHI No. 2505562		
	GENERAL MOTORS	55579846
	OPEL	1247929


HÜCO No. 135563 / HITACHI No. 2505563		
	GENERAL MOTORS	55494701
	GENERAL MOTORS	55585482
	OPEL	1247930


HÜCO No. 135565 / HITACHI No. 2505565		
	FIAT	51825679
	FIAT	51832320
	FIAT	55221054

HÜCO No. 135566 / HITACHI No. 2505566		
	VOLVO	31293881
	VOLVO	31439823

## Sensor temperatura de gas de escape

HÜCO No. 135567 / HITACHI No. 2505567		
	VOLVO	31293880
	VOLVO	31439825


HÜCO No. 135568 / HITACHI No. 2505568		
	GENERAL MOTORS	55495557
	GENERAL MOTORS	55581654
	OPEL	1247906

HÜCO No. 135569 / HITACHI No. 2505569		
	VW GROUP	059906088CN


HÜCO No. 135570 / HITACHI No. 2505570		
	VW GROUP	04L906088FT
	VW GROUP	04L906088HG


HÜCO No. 135571 / HITACHI No. 2505571		
	VW GROUP	04L906088AC
	VW GROUP	04L906088AM
	VW GROUP	04L906088BL
	VW GROUP	04L906088JD


HÜCO No. 135572 / HITACHI No. 2505572		
	CHEVROLET	55489548
	GENERAL MOTORS	55497866
	OPEL	1249064

HÜCO No. 135573 / HITACHI No. 2505573		
	CHRYSLER	51861682
	FIAT	51861682
	FIAT	55228650
	LANCIA	55228650


## Sensor presión colector de admisión


HÜCO No. 138249 / HITACHI No. 2508249		
	FIAT	504073323
	FORD	2C4612A697AA
	IVECO	504073323
	RENAULT	5010450894
	VW	2S0906051


HÜCO No. 138250 / HITACHI No. 2508250		
	DACIA	223657266R
	OPEL	93450122
	RENAULT	8200225971
	SUZUKI	1859084A01


HÜCO No. 138251 / HITACHI No. 2508251		
	MERCEDES-BENZ	A6079050400
	NISSAN	2236500QAG
	OPEL	4407979
	RENAULT	223657458R
	VAUXHALL	95517830

## Sensor árbol de levas

HÜCO No. 131875 / HITACHI No. 2501875		
	VW GROUP	06C905163B

HÜCO No. 131882 / HITACHI No. 2501882		
	BMW	12141435351
	BMW	12141438082
	BMW	12147506273
	BMW	12147518628

HÜCO No. 131892 / HITACHI No. 2501892		
	VW GROUP	04L907601
	VW GROUP	04L907601A
	VW GROUP	05E907601D

HÜCO No. 131895 / HITACHI No. 2501895		
	FIAT	9664430980
	FORD	AV6Q12K073AA
	PSA	1920QZ
	PSA	9664430980
	VOLVO	31319621

## Sensor presión

HÜCO No. 137416 / HITACHI No. 2507416



FIAT	55210304
IVECO	504102810
MITSUBISHI	1865A101
PSA	1618ET
PSA	1623137380

HÜCO No. 137423 / HITACHI No. 2507423



FORD	0741584Z03
FORD	8C3A5H295AC
FORD	8C3A9G824AB
FORD	8C3Z9J460D
FORD	C17G2807851

HÜCO No. 137424 / HITACHI No. 2507424



FORD	1778137
FORD	CV215H295AB

HÜCO No. 137427 / HITACHI No. 2507427



FORD	882316003
FORD	FS7A5H209AB
FORD	FS7A5H209AC

HÜCO No. 137429 / HITACHI No. 2507429



HYUNDAI / KIA	392102F600
HYUNDAI / KIA	392512A600
HYUNDAI / KIA	392512A610

HÜCO No. 137430 / HITACHI No. 2507430



BMW	13627805758
MINI	13627805758

HÜCO No. 137431 / HITACHI No. 2507431




GENERAL MOTORS	55570092
GENERAL MOTORS	55598778
OPEL	862088
OPEL	862104
OPEL	862113


HÜCO No. 137434 / HITACHI No. 2507434





FORD	BK2A9G824AA
FORD	WG2172959


## Resistencia, ventilador del compartimento de habitáculo


HÜCO No. 132606 / HITACHI No. 2502606		
	RENAULT	7701050890


HÜCO No. 132607 / HITACHI No. 2502607		
	VW Group	1H0959263


HÜCO No. 132608 / HITACHI No. 2502608		
	RENAULT	7701059206
	RENAULT	7701206351

HÜCO No. 132609 / HITACHI No. 2502609		
	RENAULT	7701207876


HÜCO No. 132610 / HITACHI No. 2502610		
	RENAULT	7701051433


HÜCO No. 132611 / HITACHI No. 2502611		
	RENAULT	7701057684


HÜCO No. 132612 / HITACHI No. 2502612		
	FIAT	1306599080
	FIAT	71732251
	PSA	644100000
	PSA	6441V4


HÜCO No. 132613 / HITACHI No. 2502613		
	VW GROUP	7E0959263
	VW GROUP	7E0959263A
	VW GROUP	7E0959263C


## Resistencia, ventilador del compartimento de habitáculo


HÜCO No. 132614 / HITACHI No. 2502614		
	OPEL	4409452
	OPEL	91158691
	OPEL	95525334
	RENAULT	7701050325


HÜCO No. 132616 / HITACHI No. 2502616		
	RENAULT	7701206540
	RENAULT	7701207853


HÜCO No. 132617 / HITACHI No. 2502617		
	PEUGEOT	6441CT

HÜCO No. 132618 / HITACHI No. 2502618		
	OPEL	13124714
	OPEL	13124715
	OPEL	6845780
	CHEVROLET	93312506

HÜCO No. 132619 / HITACHI No. 2502619		
	RENAULT	7701067951

HÜCO No. 132620 / HITACHI No. 2502620		
	MERCEDES-BENZ	A0018211360

HÜCO No. 132621 / HITACHI No. 2502621		
	CITROËN	6450P7

HÜCO No. 132622 / HITACHI No. 2502622		
	FORD	1774402
	FORD	1804471
	FORD	AV1118B647AB
	FORD	AV6N18B647AA



Visite nuestro canal de YouTube para los últimos videos de productos.

Visit us on  YouTube