






Visit our website

Shock Absorber

HITACHI No. 2016719 / TOKICO No. B2384		
	SUBARU	20310SA000

HITACHI No. 2016720 / TOKICO No. B2385		
	SUBARU	20310SA010


HITACHI No. 2017255 / TOKICO No. B2402		
	SUZUKI	4160151KA1
	SUZUKI	4160162J10


HITACHI No. 2017256 / TOKICO No. B2403		
	SUZUKI	4160251KD1
	SUZUKI	4160262J10


HITACHI No. 2017595 / TOKICO No. B3192		
	MITSUBISHI	MB518687
	MITSUBISHI	MB518688
	MITSUBISHI	MB518689
	MITSUBISHI	MB518970
	MITSUBISHI	MB587339

HITACHI No. 2017910 / TOKICO No. B3396		
	TOYOTA	4851080644
	TOYOTA	4851080647
	TOYOTA	4851080732
	TOYOTA	4851080734
	TOYOTA	4851080735

HITACHI No. 2017911 / TOKICO No. B3397		
	TOYOTA	4852080346
	TOYOTA	4852080348
	TOYOTA	4852080349
	TOYOTA	4852080413
	TOYOTA	4852080419

HITACHI No. 2016726 / TOKICO No. B3449		
	SUBARU	20310FG010
	SUBARU	20310FG130

HITACHI No. 2016727 / TOKICO No. B3450		
	SUBARU	20306AG000
	SUBARU	20310AG040
	SUBARU	20310AG500

HITACHI No. 2016728 / TOKICO No. B3451		
	SUBARU	20306AG010
	SUBARU	20310AG050
	SUBARU	20310AG510

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.


You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.


Astemo



Visit our website

Shock Absorber

HITACHI No. 2016717 / TOKICO No. B3504		
	SUBARU	20360SA000

HITACHI No. 2016718 / TOKICO No. B3505		
	SUBARU	20360SA010

HITACHI No. 2016849 / TOKICO No. E35021		
	MAZDA	GHY528700
	MAZDA	GHY928700
	MAZDA	GJR928700D
	MAZDA	GJY928700
	MAZDA	GLW328700

Advanced



Sustainable



Technologies



for Mobility



Astemo



Check our YouTube Channel for new videos.

Visit us on  **YouTube**