






Unidad alimentación de combustible


HÜCO No. 133138 / HITACHI No. 2503138		
	PORSCHE	95B919050
	PORSCHE	95B919050A
	VW Group	8R0919050D
	VW Group	8R0919050E


HÜCO No. 133139 / HITACHI No. 2503139		
	BMW/MINI	16119807098
	BMW/MINI	16119810567

HÜCO No. 133140 / HITACHI No. 2503140		
	RENAULT / DACIA	172022377R

HÜCO No. 133141 / HITACHI No. 2503141		
	VW Group	6R0919050D
	VW Group	6R0919050K
	VW Group	6RF919050


HÜCO No. 133142 / HITACHI No. 2503142		
	VW Group	4G0919050A

HÜCO No. 133143 / HITACHI 2503143		
	VOLVO	30778660
	VOLVO	30792391
	VOLVO	30792725
	VOLVO	8638671


HÜCO No. 133144 / HITACHI No. 2503144		
	GENERAL MOTORS	13507560
	GENERAL MOTORS	13507563
	OPEL	13515297
	OPEL	13591896

Kit servicio bomba alimentacion combustible

HÜCO No. 133232 / HITACHI No. 2503232		
	PSA	1525ER
	PSA	9647083280


HÜCO No. 133235 / HITACHI No. 2503235		
	RENAULT	172020054R

Bobina de encendido

HÜCO No. 133969 / HITACHI No. 2503969		
	FORD	2249266
	FORD	2311876
	FORD	HX7G12A366AA
	FORD	HX7G12A366AB

HÜCO No. 133973 / HITACHI 2503973		
	TOYOTA	9091902271

Sensor árbol de levas

HÜCO No. 138180 / HITACHI No. 2508180		
	FORD	1119942
	FORD	1S7F12K073AD
	MAZDA	LF0118230
	VOLVO	30658182A



Visite nuestro canal de YouTube para los últimos videos de productos.

Visit us on  YouTube