




<https://aftermarket.hitachiastemo.com/emea>


## Fuel feed unit


HÜCO No. 132768 / HITACHI No. 2502768		
	BMW	16141180504
	BMW	16141182842
	BMW	16141182843


HÜCO No. 132769 / HITACHI No. 2502769		
	VW GROUP	4E0919087H
	VW GROUP	4E0919087K


HÜCO No. 132770 / HITACHI No. 2502770		
	VW GROUP	4E0919087G
	VW GROUP	4E0919087J

HÜCO No. 132771 / HITACHI No. 2502771		
	PSA	1525CH
	PSA	1525HG
	PSA	1525Y8
	PSA	96494182

HÜCO No. 132772 / HITACHI No. 2502772		
	PSA	1525KJ
	PSA	1525Q4

HÜCO No. 132773 / HITACHI No. 2502773		
	FORD	4N519H307PJ
	VOLVO	31305130

HÜCO No. 132774 / HITACHI No. 2502774		
	FIAT	51787160
	FIAT	51875648
	FIAT	52179891
	FIAT	629100627

HÜCO No. 132775 / HITACHI No. 2502775		
	MAZDA	LF6X1335X
	MAZDA	LFJB1335X

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.


You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

**Astemo**


<https://aftermarket.hitachiastemo.com/emea>


## Fuel pump


HÜCO No. 132777 / HITACHI No. 2502777		
	VW GROUP	8E0919051B
	VW GROUP	8E0919051R


HÜCO No. 133178 / HITACHI No. 2503178		
	MERCEDES-BENZ	A2214704594


## Glow plug relay

HÜCO No. 132247 / HITACHI No. 2502247		
	MERCEDES-BENZ	A6421530379
	MERCEDES-BENZ	A6421532079
	MERCEDES-BENZ	A6421533779
	MERCEDES-BENZ	A6429005801
	MERCEDES-BENZ	A6429007801

HÜCO No. 132248 / HITACHI No. 2502248		
	MERCEDES-BENZ	A6429002700
	MERCEDES-BENZ	A6429005701
	MERCEDES-BENZ	A6429007701

HÜCO No. 132261 / HITACHI No. 2502261		
	<b>First to market!</b>	
	MERCEDES-BENZ	A6089000200
	NISSAN	1106700Q0J
	RENAULT	110679886R

HÜCO No. 132262 / HITACHI No. 2502262		
	<b>First to market!</b>	
	NISSAN	1106700Q0L
	OPEL	95529331
	RENAULT	110675590R

HÜCO No. 132263 / HITACHI No. 2502263		
	<b>First to market!</b>	
	FORD	2206042
	FORD	JX6112B533AA

<https://aftermarket.hitachiastemo.com/emea>

## Ignition coil

HÜCO No. 133958 / HITACHI No. 2503958



PORSCHE	94860210402
PORSCHE	94860210406
PORSCHE	94860210410
PORSCHE	94860210412
PORSCHE	94860210414

## Air dryer cartridge, compressed-air system

HITACHI No. 2509885



HITACHI	DRY012706
LAND ROVER	RQQ500020
LAND ROVER	VUB504700



Check our YouTube Channel for new videos.

Visit us on  **YouTube**

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service.  
If you would like to unsubscribe from the newsletter please let us know.

**Astemo**