



Visit our website

Ignition Coil

HÜCO No. 133798 / HITACHI No. 2503798



FIAT	55282087
JEEP	55282087

Crankshaft Position Sensor

HÜCO No. 137361 / HITACHI No. 2507361

Now available in Hitachi Brand.



FIAT	73502752
FORD	9S519E731AA
GENERAL MOTORS	93178045
OPEL	4708543
PSA	1920SQ

HÜCO No. 137367 / HITACHI No. 2507367

Now available in Hitachi Brand.



PSA	591891
PSA	591893
PSA	9614004500
PSA	9616806280

HÜCO No. 137372 / HITACHI No. 2507372

Now available in Hitachi Brand.



PSA	19208S
PSA	9632889780
RENAULT	9634049880

HÜCO No. 138079 / HITACHI No. 2508079

Now available in Hitachi Brand.



VW GROUP	047906433
----------	-----------

HÜCO No. 138080 / HITACHI No. 2508080

Now available in Hitachi Brand.



VW GROUP	03C906433A
VW GROUP	03C906433E
VW GROUP	045906433B
VW GROUP	032906433
VW GROUP	032906433A

HÜCO No. 138113 / HITACHI No. 2508113

Now available in Hitachi Brand.



NISSAN	23731BN700
NISSAN	2375000Q0A
RENAULT	7700100566
RENAULT	8201040861
SUZUKI	3544284CT1000

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

Astemo



Visit our website

Crankshaft Position Sensor

HÜCO No. 138114 / HITACHI No. 2508114

Now available in Hitachi Brand.



GENERAL MOTORS	9110560
NISSAN	2375000Q0F
OPEL	4402560
RENAULT	7700101970
RENAULT	8200468645

HÜCO No. 138115 / HITACHI No. 2508115

Now available in Hitachi Brand.



IVECO	504096645
MAN	51271207038
OPEL	93179850
RENAULT	5010412449
VOLVO	20513343

HÜCO No. 138117 / HITACHI No. 2508117

Now available in Hitachi Brand.



NISSAN	2379800QAC
NISSAN	2379800QAD
RENAULT	7700101969
RENAULT	8200396919
RENAULT	8200436025

HÜCO No. 138118 / HITACHI No. 2508118

Now available in Hitachi Brand.



FIAT	71739726
GENERAL MOTORS	10456604
OPEL	1238938

HÜCO No. 138120 / HITACHI No. 2508120

Now available in Hitachi Brand.



GENERAL MOTORS	90540188
OPEL	6238395
SAAB	4772232
SAAB	90464741
SAAB	9544560

HÜCO No. 138124 / HITACHI No. 2508124

Now available in Hitachi Brand.



MERCEDES-BENZ	A0031539528
MERCEDES-BENZ	A0031539528
SMART	Q0003117V002000000

HÜCO No. 138130 / HITACHI No. 2508130

Now available in Hitachi Brand.



FIAT	9662221580
FORD	2S7Q6C315AC
JAGUAR	JD61138
LAND ROVER	LR004396
PSA	1920LV

HÜCO No. 138132 / HITACHI No. 2508132

Now available in Hitachi Brand.



DACIA	8200647554
NISSAN	23731AZ70A
NISSAN	2375000Q0H
NISSAN	2375000QAH
RENAULT	8200610944

HÜCO No. 138133 / HITACHI No. 2508133

Now available in Hitachi Brand.



NISSAN	2375000QAB
OPEL	4414098
RENAULT	8200443891
SUZUKI	3322067J00000
VOLVO	30617112

HÜCO No. 138136 / HITACHI No. 2508136

Now available in Hitachi Brand.





TOYOTA	9091905043
--------	------------





Visit our website

Crankshaft Position Sensor


HÜCO No. 138140 / HITACHI No. 2508140		
Now available in Hitachi Brand.	VW GROUP	06A906433C
		


HÜCO No. 138142 / HITACHI No. 2508142		
Now available in Hitachi Brand.	ALFA ROMEO	60814769
	ALFA ROMEO	60816553
	FIAT	46446873
	GENERAL MOTORS	97323554
	OPEL	851366

HÜCO No. 138155 / HITACHI No. 2508155		
Now available in Hitachi Brand.	VW GROUP	06A906433K
		

HÜCO No. 138159 / HITACHI No. 2508159		
Now available in Hitachi Brand.	VW GROUP	071957147
	VW GROUP	078906433A

HÜCO No. 138161 / HITACHI No. 2508161		
Now available in Hitachi Brand.	VW GROUP	06A906433G
	VW GROUP	06A906433L
	VW GROUP	06A906433B
	VW GROUP	06A906433N

HÜCO No. 138169 / HITACHI No. 2508169		
Now available in Hitachi Brand.	FIAT	9643695780
	FORD	1231925
	FORD	3M5Q9E731AA
	PSA	1920GJ
	VOLVO	8653703

HÜCO No. 138176 / HITACHI No. 2508176		
Now available in Hitachi Brand.	HYUNDAI / KIA	3918023500
	HYUNDAI / KIA	3918023910

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

Astemo



Visit our website

Camshaft Position Sensor

HÜCO No. 137378 / HITACHI No. 2507378

Now available in Hitachi Brand.



FORD	1148056
FORD	2S6Q12K073AA
MAZDA	Y40118230
PSA	1920EJ
TOYOTA	SU00100641

HÜCO No. 137389 / HITACHI No. 2507389

Now available in Hitachi Brand.



VW GROUP	07K907601
VW GROUP	07K907601A

HÜCO No. 138081 / HITACHI No. 2508081

Now available in Hitachi Brand.



VW GROUP	047907601
----------	-----------

HÜCO No. 138085 / HITACHI No. 2508085

Now available in Hitachi Brand.



FORD	3M216B288AA
FORD	XM216B288AA
VW GROUP	038957147A
VW GROUP	045957147A
VW GROUP	045957147B

HÜCO No. 138091 / HITACHI No. 2508091

Now available in Hitachi Brand.



VW GROUP	030907601
VW GROUP	030907601D
VW GROUP	03D907601
VW GROUP	03D907601A

HÜCO No. 138122 / HITACHI No. 2508122

Now available in Hitachi Brand.



FIAT	46481640
FIAT	60814770
OPEL	6235667
SAAB	93179513
SUZUKI	3322079JU0000

HÜCO No. 138126 / HITACHI No. 2508126

Now available in Hitachi Brand.



CHRYSLER	K05101122AA
MERCEDES-BENZ	A0031538328
MERCEDES-BENZ	A0041530728
MERCEDES-BENZ	A0041536928
VW	0B8927321

HÜCO No. 138128 / HITACHI No. 2508128

Now available in Hitachi Brand.



FORD	1111037
FORD	YS6A12K073AB
MAZDA	C20118230
VOLVO	30711663

HÜCO No. 138137 / HITACHI No. 2508137

Now available in Hitachi Brand.



OPEL	1238425
VAUXHALL	90536064

HÜCO No. 138158 / HITACHI No. 2508158

Now available in Hitachi Brand.





VW GROUP	06A905161B
VW GROUP	06A905161C




Visit our website


Camshaft Position Sensor


HÜCO No. 138168 / HITACHI No. 2508168		
Now available in Hitachi Brand.	VW GROUP	070907601A
		


HÜCO No. 138178 / HITACHI No. 2508178		
Now available in Hitachi Brand.	FIAT	46798364
	GENERAL MOTORS	93190702
	OPEL	1235268
	OPEL	55216243
		


HÜCO No. 138300 / HITACHI No. 2508300		
Now available in Hitachi Brand.	PSA	19207V
	FORD	9M5Q12K073AA
	MITSUBISHI	MN982271
	SUZUKI	3322067J10000
	VOLVO	30711105
		

Sensor, exhaust pressure

HÜCO No. 137412 / HITACHI No. 2507412		
Now available in Hitachi Brand.	MITSUBISHI	1865A119
	VW GROUP	07Z906051
	VW GROUP	07Z906051A
		

HÜCO No. 137413 / HITACHI No. 2507413		
Now available in Hitachi Brand.	VOLVO	31319635
	VOLVO	31319635
		

HÜCO No. 137415 / HITACHI No. 2507415		
Now available in Hitachi Brand.	LAND ROVER	C2Z13154
	LAND ROVER	LR023131
	LAND ROVER	LR028861
	LAND ROVER	LR030030
	LAND ROVER	LR070166
		

HÜCO No. 137418 / HITACHI No. 2507418		
Now available in Hitachi Brand.	FIAT	51855119
	IVECO	5801356473
	OPEL	93185556
	PEUGEOT	1610531380
	SUZUKI	1859062M00000
		

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.


Astemo




Visit our website

Sensor, exhaust pressure


HÜCO No. 137421 / HITACHI No. 2507421

	Now available in Hitachi Brand.	GENERAL MOTORS	25182883
		OPEL	4818222


HÜCO No. 137426 / HITACHI No. 2507426

	Now available in Hitachi Brand.	mitsubishi	1865A328

HÜCO No. 137432 / HITACHI No. 2507432

	Now available in Hitachi Brand.	MAZDA	S550182B2
		MAZDA	S550182B2A

HÜCO No. 137433 / HITACHI No. 2507433

	Now available in Hitachi Brand.	VOLVO	31370160
		VOLVO	31697984



Updated Tokico catalogue available.



HALL 2
BOOTH C32

Come and see us in Dubai
at Automechanika 2024!

December 10-12
Dubai