



Visit our website

## Sensor, fuel pressure

HÜCO No. 131916 / HITACHI No. 2501916



FIAT	9658227880
PSA	1920GW

HÜCO No. 131917 / HITACHI No. 2501917



FIAT	9670076780
FIAT	9813735580
PSA	1606643580

HÜCO No. 131920 / HITACHI No. 2501920



VW GROUP	03L906051
VW GROUP	03L906054
VW GROUP	03L906054A

HÜCO No. 131922 / HITACHI No. 2501922



RENAULT	8200669695
---------	------------

HÜCO No. 131923 / HITACHI No. 2501923



VW GROUP	05A906051
----------	-----------

HÜCO No. 131924 / HITACHI No. 2501924



FIAT	9664613880
FIAT	9665400680
FORD	8C1Q9D280AA
MITSUBISHI	1465A034
PSA	1570P1

HÜCO No. 131925 / HITACHI No. 2501925



HYUNDAI	315004X400
KIA	315004X400
MERCEDES-BENZ	A6460700395

HÜCO No. 131926 / HITACHI No. 2501926



VW GROUP	059130758E
----------	------------

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.


You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.


**Astemo**





Visit our website


## Sensor, fuel pressure

HÜCO No. 131927 / HITACHI No. 2501927		
	VW GROUP	059130758K


HÜCO No. 131928 / HITACHI No. 2501928		
	PSA	9676643880

HÜCO No. 131929 / HITACHI No. 2501929		
	NISSAN	1752000Q2E
	NISSAN	1752000Q4F
	RENAULT	1506519062

HÜCO No. 131930 / HITACHI No. 2501930		
	FIAT	9814383880
	OPEL	3556282
	OPEL	9814383880
	PSA	9663305480
	PSA	9814383880

HÜCO No. 131932 / HITACHI No. 2501932		
	FIAT	5802186887
	FORD	9S519G756AB
	OPEL	93185626
	SUZUKI	1576084E51000
	VOLVO	30677300

## Relay, main current


HITACHI No. 2502222		
	<b>on request</b>	
	RENAULT	7700810929
	RENAULT	7700844253
	RENAULT	7701032100




Visit our website


## Shock absorbers

HITACHI No. 2016709 / TOKICO No. B2399		
	MAZDA	DC2034900
	MAZDA	DC2234900
	MAZDA	DC3534900
	MAZDA	DC3734900
	TOKICO	B2399

HITACHI No. 2016710 / TOKICO No. B2398		
	MAZDA	DC2034700
	MAZDA	DC2234700
	MAZDA	DC3534700
	MAZDA	DC3734700
	TOKICO	B2398

HITACHI No. 2016898 / TOKICO No. E20028		
	TOKICO	E20028
	TOYOTA	4853052F30
	TOYOTA	4853080437
	TOYOTA	4853080486

HITACHI No. 2017200 / TOKICO No. B2316		
	HONDA	51601SNA916
	HONDA	51605SNA905
	HONDA	51605SNLT04
	TOKICO	B2316

HITACHI No. 2017963 / TOKICO No. B2317		
	HONDA	51602SNA916
	HONDA	51606SNA905
	HONDA	51606SNLT04
	TOKICO	B2317

HITACHI No. 2017967 / TOKICO No. E20019		
	HONDA	52610SNLT03
	HONDA	52610SNLT031
	TOKICO	E20019



Check our YouTube Channel for new videos.

Visit us on  **YouTube**

OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.

**Astemo**